VOYAGER 8200 UC FIRMWARE RELEASE NOTES

Version 700
May 2021

What's new

- Medium key press on mute button places a call on hold or resumes a call that is on hold

Resolved Issues

- Enable HD Voice by default
- Improved time to reconnect
- Minor bug fixes

Version 667
April 2020

Whats new

- Microsoft Teams certification – pressing headset button will now invoke the Microsoft Teams desktop application
- Update company branding in USB descriptors to Poly

Version 552
July 2019

What's new

- Increase maximum receive volume
- Disable TWA (Time-Weighted Average) limiting and reporting while listening to multimedia. TWA in telephony mode is unchanged and still enabled (configurable by Plantronics Manager Pro and Plantronics Hub)

Resolved Issues

- Occasional lip-sync issues while watching videos
- iOS language change issue
- With Plantronics Hub displaying incorrect talk time remaining for headset
- Compatibility issue with Mitel 6930/6940 desk phones, where headset cannot be repaired with desk phones after the desk phone is rebooted

Version 402
June 2018

Whats new

- Added support for Plantronics Manager Pro Reports Acoustic Events with Plantronics Hub for Desktop
- Added support for Plantronics Manager Pro with Plantronics Hub for iOS and Android

Resolved Issues

- Improved PC audio when also connected to a mobile phone
- Fixed issue where battery status LED indication was not being displayed in certain instances
- Fixed issue where removing the headset did not always pause the music

Version 218

December 2017 Voyager 8200 UC firmware version 218

What's New

- Resolve audio squealing issue
- Clicking or pop noise on Skype for Bussines Call

Version 116
September 25, 2017
What's New

- Support for Bluetooth Radio Link Quality report in Conversation Analysis Suite of Plantronics Manager Pro

Version 115
July 2017

- Initial Release